

**SAS Superstructure**

Location: 04-SF-80-13.2 / 13.9

Client Name: CalTrans

Run date 21-Nov-14

Time 10:15 PM

**Daily Diary Report by Bid Item**

Contract No.: 04-0120F4

Diary #: 123 Const Calendar Day: 15

Date: 19-Jun-2012 Tuesday

Inspector Name: Altamirano, Victor

Title: Transportation Engineer

Inspection Type:

Shift Hours:

Break:

Over Time:

Federal ID:

Location:

Reviewer: Schmitt, Alex

Approved Date:

Status: Submit

**04-0120F4  
04-SF-80-13.2/13.9  
Self-Anchored  
Suspension Bridge****Weather****Temperature** 7 AM 50 - 60 12 PM 50 - 60 4PM 50 - 60**Precipitation****Condition**Working Day ☒ If no, explain:**Diary:**

Dispute

**Cable Band**

Inspector: Victor Altamirano (8 hours reg. and 3 hours OT)

Date: 061912

**Field Operation:**

(1) I took gap and circumference measurements of the cable band gaps and of the main cable after workers re-tensioned cable band bolts to 19.343kpsi. These measurements were for cable bands located at PP 26E, 24E and 22E on the South Side span